This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Appl. No. 10/729,066 Amendment dated June 25, 2004 Reply to Office Action of March 31, 2004 Replacement Figure 8







Figure 8



Figure 7


Appl. No. 10/729,066 Amendment dated June 25, 2004 Reply to Office Action of March 31, 2004 Replacement Figure 7

Normalized Amplitude (volts)



Appl. No. 10/729,066 Amendment dated June 25, 2004 Reply to Office Action of March 31, 2004 Replacement Annotated Figure 7





Appl. No. 10/729,066 Amendment dated June 25, 2004 Reply to Office Action of March 31, 2004 Deleted Figure 7b 5 -5 0 5 Off Boresight Angle (degrees) Figure 7b modeling for this figure need LM to do the

Variation In Beta Angle Error

This figure is incorrect,

0.8

0.6

(stlov) abutilqmA basilsm10N

Appl. No. 10/729,066 Amendment dated June 25, 2004 Reply to Office Action of March 31, 2004 Replacement Annotated Figure 8

